


CP60 Trevilly Project Summary



The Trevilly section of the South West Coast Path is located close to Mill Bay (Nanjizel) near to Land's End. This popular section of coast path predominantly consists of maritime heath on granite based geology.

The steep nature of the valleys in this area means that often the coast path is subject to erosion, brading and areas of poaching which is caused by walkers looking for easier alternatives than the eroded walked route. The nature of the landscape means that even the smallest erosion problems are visible from a distance.

The aim of this project was two fold

1. Deal with the aesthetic problems created by the erosion
2. Provide a better walking surface for walkers

Granite stepping stones were used to provide a clear surface for walkers. Additional drainage ditches have been cut to enhance the drainage of the area. The benefits from this project include improved access to the beach at Nanjizel from the main access point at Land's End.

8x stepping stones & shallow ditches.



1x stepping stone.



1x stepping stones.



